

Form 3

NAP 5 - SHORNHEAD LIGHT

PLA Navigational SMS
Navigational Advisory Panel Review.

NAP Date:	04/04/2002	Scheduled Review Date:	**/**/20**	Owner:	Harbour Master Lower	Frequency:	Months/Year(s)
-----------	------------	------------------------	------------	--------	----------------------	------------	----------------

Panel Members:

Name	Organisation	Name	Organisation	Name	Organisation
G Dickins	PLA	A McKay	PLA	P Steen	PLA
R Taylor	PLA	G Price	PLA	D Pride	J J Prior
J Skellorn	RYA	N Mayston	PLA		

Reference	Detail	Observation/Recommendation
	Shornmead lighthouse is showing signs of impending collapse, a replacement is required, review of light, sectors and associated lights at Northfleet undertaken in connection with this	<p>Prior consultation by Notice to River Users resulted in a requirement for Shornmead and Northfleet Upper lights to be retained and possible removal of Northfleet Lower.</p> <p>Panel recommends.</p> <p>Sector lights still preferred – better visibility and cut off desirable.</p> <p>Lower Hope red section not required.</p> <p>Gravesend white sector to be opened to the north – cutting N bank at cargo jetty.</p> <p>Possible re-positioning to allow south channel edge to be defined. If not possible the Northfleet Lower or equivalent to be retained.</p>

Panel Chairman:	G DICKINS	Signature:	
-----------------	-----------	------------	---