

Form 3

NAP 2 - Dart 8

**PLA Navigational SMS
Navigational Advisory Panel Review.**

NAP Date:	04/02/2002	Scheduled Review Date:	See below	Owner:	HML	Frequency:	Months/Year(s)
-----------	------------	------------------------	-----------	--------	-----	------------	----------------

Panel Members:

Name	Organisation	Name	Organisation	Name	Organisation
Capt R Stanbrook	PLA[DHM(L)]	Capt M Thompson	Dart Line [Master Dart8]	Mr G Negus	PLA [VTSO]
Capt R Taylor	PLA [Pilot]	Capt T McGown	R Laphorn [Master]		
Capt A Hill	MPA [Pilot]	Mr B Goldman	PLA [VTSM]		

Reference	Detail	Observation/Recommendation
2002/2	Outbound "Dart 8" misidentified inbound "Undine" for Medway bound "Summer Flower" resulting in a near miss with the "Undine" in the Oaze Deep.	<p>PLASMA Hazard Reference 161 (review ????) relates.</p> <p>Summary of recommendations:</p> <ul style="list-style-type: none"> • South Oaze Buoy to be renamed East Oaze. • VTS procedures in the Oaze Precautionary Area to be considered by the Pilot/VTS Working Group. • Deep-draft vessels of over 12m draft to be reported in traffic broadcasts to the east of Sea Reach 1 buoy. (This recommendation is not directly related to the identified hazard).

Panel Chairman:	R Stanbrook	Signature:	
-----------------	-------------	------------	--